


MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 35, Township 10 North, Range 1 East,


Monument Description & Remarks: 3/4" Iron Pipe 0.6' Above Ground On W. Side Of Broken Sandstone With "X"



COMPLETED BY B. E. Bledsoe

I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 27th day of December, 2004 A.D.

B. E. Bledsoe
 Indiana Registered Land Surveyor No. S0559



MONUMENT RECORD

State of Indiana - County of Monroe

Section: Thirty five (35)

Township: 10 North

Range: 1 East

Corner ID: Ben No S-23



Monument Description & Remarks: East 1/4 corner of section; found 11/16" Iron Pipe next to broken sandstone monument with "+". Pipe was 0.6' above ground.

References on file: Doug Curry, L.S. #890006, survey recorded in Book 3, Page 437, Recorder's Office; Legal Survey Book 2, Page 257, Surveyor's Office.

RECOVERY TIE DRAWING

Field Book 97-01 Page No. 6

USGS Unionville Quad



• At Corner

A - Iron Pipe next to broken sandstone w/ "+"

B - South 56 degrees West, 23.48' from stone
PK nail in 6" Tulip Poplar

C - North 24 degrees West, 8.00' from stone
PK nail in 20" Beech, survey marker sign set 4.5' up

D - North 40 degrees East, 27.00' from stone
PK nail in base of 10" Tulip Poplar

Not To Scale

Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 7th day of January, 1997.

Kevin Enright



Administered by: *Surveyor*

BOARD



Indiana R.L.S. No. *N/a*